

CLIENT: 1128441 Alberta LTD. DATE: June-18-13  
 CLIENT JOB# Report #  
 CLIENT P.O.: JOB NO. 19054  
 CERTIFICATION # PAGE: 1 OF 1

**SAFETY IS ALWAYS JOB #1**

MAGNETIZATION		EQUIPMENT OWNER & BILLING ADDRESS	
METHOD	Yoke	1128441 Alberta LTD.	
CURRENT	Alternating	Ray Anderson 403-548-1995	
FIELD	Continuous AC		
PARTICLE		EQUIPMENT IDENTIFICATION	
MEDIUM	Wet	65 ton 8 5/8 AOT S.N. 40054	
TYPE	Visible	KS 808	
APPLICATION	Spray on Fluorescent		
CODES AND STANDARDS		EQUIPMENT EMPLOYED	
PROCEDURE	ATI-MT-3.0	Parker B310	
TECHNIQUE #1	MT-19	Spetroline Black Light and Spray Bottle	
INSPECTION CODE	CAODC, ASME V		
CALIBRATION STD.	ASME V, Article 7, T760	CONSUMABLES	
SURFACE CONDITION	Painted	14AM FLORESCENT BATH	
DEMAGNIFICATION	ASME V, Article 7, T778		

**JOB SCOPE /WORK PERFORMED**

Magnetic particle inspection and a full visual inspection was performed on the above mentioned equipment. Two small (<15mm) indications were found in a non-critical area. This was repaired by DaPaJo (procedure DPI-3A) and no relevant indications were found after this repair.

**ENGINEERS STAMPS**

**PERMIT TO PRACTICE**  
FIRTH ENGINEERING LTD.

Signature: *Lund*  
Date: *June 20, 2013*

PERMIT NUMBER: P 6554  
The Association of Professional Engineers and Geoscientists of Alberta

TECHNICIAN				
Troy Gangl CGSB #11771				
<i>T. Gangl</i>				
Time, Travel, P/W & Consumables & Cost Codes				
Date:	In	Out	Total Hr's	Km's
			2hrs	
One Man:	<input checked="" type="checkbox"/>	Two Man:	<input type="checkbox"/>	Office Code:
Consumables:	min	Engineering:	Y <input checked="" type="checkbox"/> N <input type="checkbox"/>	

