



Ideal Inspection

(a division of Ideal Oilfield Construction Ltd.)
P.O Box 1473
Brooks, Alberta
T1R 1C3
Phone: 403-362-2843 Fax: 403-362-2862

INSPECTION REPORT

| | | | | | |
|--|--|---------------------------------------|---|---|---------------------------------------|
| Client: K&S Power Tongs | | Location: DaPaJo Construction Limited | | Date: May 10, 2013 | |
| P.O. : | | Work Order : 2248j | | Report : 3843 | |
| Page : 1 of 1 | | Unit : 1104 | S/N: 070283627 | Inspection: Magnetic Particle | |
| Parts Examined: Web Wilson 11 3/4" 50 Ton Side Door Casing Elevator | | | | | |
| Surface Condition: Painted | | | Material Temperature: 10° Celsius | | |
| Procedure: MPI-DPJ-001 | | | Code: ASME Section V, ASTM E709 | | |
| Equipment: Parker B 310 Contour Probe | | | | | |
| Method: Magnetic Particle, AC Continuous, Wet Florescent Method | | | | | |
| Test Medium: Magnaglow 14 HF Florescent Prepared Bath | | | | | |
| Test Results: | | | Engineer's Approval: | | |
| No defects were found at the time of this inspection. | | |  | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Photos: | | | | | |
|  | | | | | |
| Technician: John Frances | | CGSB #: 7062 | Signature:  | Assistant: Tyler Nevison | |
| Repairs Complete | | Yes <input type="checkbox"/> | No <input type="checkbox"/> | N/A <input checked="" type="checkbox"/> | X <input type="checkbox"/> |
| Acceptable For Service | | | | Yes <input type="checkbox"/> | X <input checked="" type="checkbox"/> |
| No <input type="checkbox"/> | | | | | |